


Important Safety Information

LOGIK LVD7W15 & LVD7W18



For products sold from 2015 to Sept 2019
with Serial numbers up to 1928031213

In 2019 we identified the top cover on some products can become deformed if subjected to significant weight (for example, it is sat on or heavy items are placed on top of it).

Details advised: If liquid is spilt on a deformed cover, the liquid could drip inside the appliance. We believe the likelihood of this scenario occurring is very low. If liquid does drip inside this may not be problematic but it could cause an electrical short circuit which may mean the machine stops working or, in an extreme case, a fire.

Customers were invited to contact us should they wish to have a replacement improved top cover fitted.

Any top cover that had not been subjected to significant weight or suffered spillage, the tumble dryer could continue to be used.

Additional information for when using any tumble dryer:

Although this campaign is no longer in operation we would like to take the opportunity to share with you guidance on the safe use of your tumble dryer. You must not sit, stand or place heavy items on the top cover of your tumble dryer. Please also exercise caution when handling liquid near your tumble dryer.

To help maintain your tumble dryer and to get the very best performance it is important that the lint filter is cleaned after every cycle, and proper venting should be established in accordance with the original instructions for use.

These simple actions will ensure you use the minimum amount of energy when using your dryer and always get the best possible results.

Should you need a copy of an instruction book please visit www.currys.co.uk

For help and support, please visit our help and support page: [Help & Support | Currys](#)

How to find your serial number

